



Scoda Aeronáutica Ltda
Estrada Municipal IPN 020 km 0,1
Ipeúna – SP, Brazil.
PHONE: (19) 3576-1292
ZIP CODE: 13537-000
www.scodaeronautica.com.br

SAFETY ALERT

SA_SPLS_001
Revision 02

Released Date: **November 29th, 2019**
Effective Date: **July 09th, 2020**

Page 1 de 4

SAFETY ALERT

SA_SPLS_001

INSPECTION FOR APPLICABILITY OF ROTAX ASB-912I-011iS

Application of Notes, Cautions and Warnings

NOTES, CAUTIONS and **WARNINGS** are used in this document to emphasize instructions and information considered to be unusual or critical. A **NOTE, CAUTIONS** and **WARNINGS** may appear in the text either before or after the instruction(s) to which it applies, depending on the relative significance of the information. The conditions that warrant the use of **NOTES, CAUTIONS** and **WARNINGS** are defined below:

WARNING

IDENTIFIES AN INSTRUCTION, WHICH IF NOT FOLLOWED MAY CAUSE SERIOUS INJURY OR EVEN DEATH

CAUTION

Denotes an instruction which if not followed, may severely damage the aircraft or could lead to suspension of warranty

NOTE

Information useful for better handling



SAFETY ALERT

Scoda Aeronáutica Ltda
Estrada Municipal IPN 020 km 0,1
Ipeúna – SP, Brazil.
PHONE: (19) 3576-1292
ZIP CODE: 13537-000
www.scodaeronautica.com.br

SA_SPLS_001
Revision 02

Page 2 de 4

Released Date: **November 29th, 2019**
Effective Date: **July 09th, 2020**

1. Planning Information

NOTE

SCODA AERONAUTICA cannot accept any responsibility for the quality of work performed. Please refer to the last revision of the Advisory Circular 43.13 – 1B Acceptable Methods, Techniques, and Practices Aircraft Inspection and Repair.

1.1. Affected Aircraft

Type: Super Petrel
Model: LS
Serial Number: All aircraft equipped with fuel pump assy. serial number affected by the referred Rotax Alert Service Bulletin
Applicable Countries: All

1.2. Reason

Rotax has issued a new revision of the **MANDATORY** ASB-912i-011iS for Engine Type 912 i (Series), which is applicable to individual Super Petrel LS aircraft as indicated by:

- a) Fuel Pump Assy.

1.3. Subject

Replacement of fuel pump assy. for ROTAX Engine Type 912 i (Series)

1.4. Personnel Qualifications

According to Rotax ASB instructions

1.5. References

ASB-912i-011iSR1 - November 27th, 2019

1.6. Superseded Documents

N/A

1.7. Contact Details

For further information on performing this SA, contact us to the following email address:

engineering@scodaero.com.br

**SAFETY ALERT****Scoda Aeronáutica Ltda**

Estrada Municipal IPN 020 km 0,1

Ipeúna – SP, Brazil.

PHONE: (19) 3576-1292

ZIP CODE: 13537-000

www.scodaeronautica.com.br**SA_SPLS_001****Revision 02****Page 3 de 4**Released Date: **November 29th, 2019**Effective Date: **July 09th, 2020****1.8. Disclaimer**

This Safety Alert has been generated with utmost care. Nevertheless errors and misunderstandings can never be fully excluded. In case of any doubts, the applicant is requested to contact Scoda Aeronáutica Ltda immediately to clarify the issue.

2. Instructions

1. Remove the baggage compartment.
2. The fuel pump assembly is located behind the baggage compartment fixed on the main bulkhead.
3. Check the serial number of the fuel pump assembly. If the fuel pump is affected, please follow the instructions of the Rotax Alert Service Bulletin.

