



Scoda Aeronáutica Ltda
Estrada Municipal IPN 020 km 0,1
Ipeúna – SP, Brazil.
PHONE: (19) 3576-1292
ZIP CODE: 13537-000
www.scodaeronautica.com.br

SERVICE LETTER

SL_SPXP_009
Revision 00

Page 1 de 3

Released Date: September 15th, 2026
Effective Date: September 15th, 2026

SERVICE LETTER

SL_SPXP_009

SPXP Maintenance Manual New Revision (Rev 07)

Application of Notes, Cautions and Warnings

NOTES, CAUTIONS and **WARNINGS** are used in this document to emphasize instructions and information considered to be unusual or critical. A **NOTE, CAUTIONS** and **WARNINGS** may appear in the text either before or after the instruction(s) to which it applies, depending on the relative significance of the information. The conditions that warrant the use of **NOTES, CAUTIONS** and **WARNINGS** are defined below:

WARNING

IDENTIFIES AN INSTRUCTION, WHICH IF NOT FOLLOWED MAY CAUSE SERIOUS INJURY OR EVEN DEATH

CAUTION

Denotes an instruction which if not followed, may severely damage the aircraft or could lead to suspension of warranty

NOTE

Information useful for better handling



SERVICE LETTER

Scoda Aeronáutica Ltda
Estrada Municipal IPN 020 km 0,1
Ipeúna – SP, Brazil.
PHONE: (19) 3576-1292
ZIP CODE: 13537-000
www.scodaeronautica.com.br

SL_SPXP_009
Revision 00

Page 2 de 3

Released Date: September 15th, 2026
Effective Date: September 15th, 2026

1. Planning Information

NOTE

SCODA AERONAUTICA cannot accept any responsibility for the quality of work performed. Please refer to the last revision of the Advisory Circular 43.13 – 1B Acceptable Methods, Techniques, and Practices Aircraft Inspection and Repair.

1.1. Affected Aircraft

Type:	Super Petrel
Model:	XP
Serial Number:	All
Applicable Countries:	Not Limited

1.2. Reason

In view of necessary updating and standardization of the Maintenance Procedures of the Super Petrel XP and the publication of the new FAA Accepted Consensus Standards (MOSAIC rules), a new revision of the Maintenance Manual has been issued covering all Super Petrel XP fleet.

1.3. Subject

New revision of the Super Petrel XP Maintenance Manual.

This new revision of the Maintenance Manual is intended to assist the aircraft operator and owner in achieving the proper maintenance procedures and consequently ensure the airworthy of the aircraft.

1.4. Compliance

INFORMATION

1.5. References

AMM_XP_001_07_Aircraft Maintenance Manual

1.6. Contact Details

For further information on performing this SL, contact us to the following email address:

engineering@scodaero.com.br

1.7. Disclaimer

This Service Letter has been generated with utmost care. Nevertheless, errors and misunderstandings can never be fully excluded. In case of any doubts, the applicant is requested to contact Scoda Aeronáutica Ltda immediately to clarify the issue.

	SERVICE LETTER	
	Scoda Aeronáutica Ltda Estrada Municipal IPN 020 km 0,1 Ipeúna – SP, Brazil. PHONE: (19) 3576-1292 ZIP CODE: 13537-000 www.scodaeronautica.com.br	SL_SPXP_009 Revision 00
Page 3 de 3		Released Date: September 15 th , 2026 Effective Date: September 15 th , 2026

2. Instructions

- A) Remove any pages of the AMM_XP_001_06 affected by a change and replace them with the revision pages of the superseded Maintenance Manual AMM_XP_001_07.
- B) Alternative to removing and/or replacing individual pages, the owner / operator can also print out a whole new maintenance manual in its current revision.

→ The new revision of the Super Petrel XP Maintenance Manual is available on Scoda's Aeronáutica website by clicking on:

https://www.scodaeronautica.com.br/blog_anexos/bc9620db3760c1d6c86524c230b1fe84.pdf **(Full Manual)**

→ In order to facilitate the upgrade of the Maintenance Manual already printed, revision pages are available on Scoda's Aeronáutica website by clicking on:

https://www.scodaeronautica.com.br/blog_anexos/bf19eb053882df7ed9981df93a5903af.pdf **(Revised Pages)**

With this, all owner/operator and mechanics can download and/or consult the document.