



SERVICE LETTER

Scoda Aeronáutica Ltda
Estrada Municipal IPN 020 km 0,1
Ipeúna – SP, Brazil.
PHONE: (19) 3576-1292
ZIP CODE: 13537-000
www.scodaeronautica.com.br

SL_SPLS_004
Revision 00

Page 1 de 3

Released Date: **April 18th, 2022**
Effective Date: **April 18th, 2022**

SERVICE LETTER

SL_SPLS_004

INSPECTION FOR APPLICABILITY OF ROTAX SB-912i-013

Application of Notes, Cautions and Warnings

NOTES, CAUTIONS and **WARNINGS** are used in this document to emphasize instructions and information considered to be unusual or critical. A **NOTE, CAUTIONS** and **WARNINGS** may appear in the text either before or after the instruction(s) to which it applies, depending on the relative significance of the information. The conditions that warrant the use of **NOTES, CAUTIONS** and **WARNINGS** are defined below:

WARNING

IDENTIFIES AN INSTRUCTION, WHICH IF NOT FOLLOWED MAY CAUSE SERIOUS INJURY OR EVEN DEATH

CAUTION

Denotes an instruction which if not followed, may severely damage the aircraft or could lead to suspension of warranty

NOTE

Information useful for better handling



SERVICE LETTER

Scoda Aeronáutica Ltda
Estrada Municipal IPN 020 km 0,1
Ipeúna – SP, Brazil.
PHONE: (19) 3576-1292
ZIP CODE: 13537-000
www.scodaeronautica.com.br

SL_SPLS_004
Revision 00

Page 2 de 3

Released Date: **April 18th, 2022**
Effective Date: **April 18th, 2022**

1. Planning Information

NOTE

SCODA AERONAUTICA cannot accept any responsibility for the quality of work performed. Please refer to the last revision of the Advisory Circular 43.13 – 1B Acceptable Methods, Techniques, and Practices Aircraft Inspection and Repair.

1.1. Affected Aircraft

Type:	Super Petrel
Model:	LS
Serial Number:	All aircraft affected by the referred Rotax Service Bulletin
Applicable Countries:	All

1.2. Reason

Rotax has issued a **MANDATORY** SB-912i-013 for Engine Type 912 i (Series), which is applicable to individual Super Petrel LS aircraft as indicated by:

- Fuel Pump serial number

1.3. Subject

Replacement of electrical fuel pump(s) for ROTAX® Aircraft Engines

1.4. Personnel Qualifications

According to Rotax SB instructions

1.5. References

- SB-912i-013 / SB-915i-012, Initial Issue April 11th, 2022



SERVICE LETTER

Scoda Aeronáutica Ltda
Estrada Municipal IPN 020 km 0,1
Ipeúna – SP, Brazil.
PHONE: (19) 3576-1292
ZIP CODE: 13537-000
www.scodaeronautica.com.br

SL_SPLS_004
Revision 00

Page 3 de 3

Released Date: **April 18th, 2022**
Effective Date: **April 18th, 2022**

1.6. Superseded Documents

N/A

1.7. Contact Details

For further information on performing this SL, contact us to the following email address:

engineering@scodaero.com.br

1.8. Disclaimer

This Service Letter has been generated with utmost care. Nevertheless errors and misunderstandings can never be fully excluded. In case of any doubts, the applicant is requested to contact Scoda Aeronáutica Ltda immediately to clarify the issue.