



Scoda Aeronáutica Ltda
Estrada Municipal IPN 020 km 0,1
Ipeúna – SP, Brazil.
PHONE: (19) 3576-1292
ZIP CODE: 13537-000
www.scodaeronautica.com.br

SERVICE BULLETIN

SB_SPLS_015
Revision 01

Page 1 de 5

Released Date: **June 23rd, 2020**
Effective Date: **July 09th, 2020**

SERVICE BULLETIN

SB_SPLS_015

ENGINE OIL DECAL

Application of Notes, Cautions and Warnings

NOTES, CAUTIONS and **WARNINGS** are used in this document to emphasize instructions and information considered to be unusual or critical. A **NOTE, CAUTIONS** and **WARNINGS** may appear in the text either before or after the instruction(s) to which it applies, depending on the relative significance of the information. The conditions that warrant the use of **NOTES, CAUTIONS** and **WARNINGS** are defined below:

WARNING

IDENTIFIES AN INSTRUCTION, WHICH IF NOT FOLLOWED MAY CAUSE SERIOUS INJURY OR EVEN DEATH

CAUTION

Denotes an instruction which if not followed, may severely damage the aircraft or could lead to suspension of warranty

NOTE

Information useful for better handling

1. Planning Information

NOTE

SCODA AERONAUTICA cannot accept any responsibility for the quality of work performed. Please refer to the last revision of the Advisory Circular 43.13 – 1B Acceptable Methods, Techniques, and Practices Aircraft Inspection and Repair.

1.1. Affected Aircraft

| | |
|-----------------------|--------------|
| Type: | Super Petrel |
| Model: | LS |
| Serial Number: | All |
| Applicable Countries: | All |

1.2. Reason

The Rotax oil tank cap has an icon printed in order to indicate engine oil (see picture below).



However based on field reports and in the continuous optimization of quality and safety an engine oil decal installation on the upper engine cowling has been introduced.

1.3. Subject

Engine Oil Decal installation



SERVICE BULLETIN

Scoda Aeronáutica Ltda
Estrada Municipal IPN 020 km 0,1
Ipeúna – SP, Brazil.
PHONE: (19) 3576-1292
ZIP CODE: 13537-000
www.scodaeronautica.com.br

SB_SPLS_015
Revision 01

Page 3 de 5

Released Date: **June 23rd, 2020**
Effective Date: **July 09th, 2020**

1.4. Compliance

RECOMMENDED

1.5. Type of Maintenance

N/A

1.6. Personnel Qualifications

N/A

1.7. Release to Service

N/A

1.8. Weight and Balance

Not Affected

1.9. References

N/A

1.10. Superseded Documents

N/A

1.11. Contact Details

For further information on performing this SB, contact us to the following email address:

engineering@scodaero.com.br



SERVICE BULLETIN

Scoda Aeronáutica Ltda
Estrada Municipal IPN 020 km 0,1
Ipeúna – SP, Brazil.
PHONE: (19) 3576-1292
ZIP CODE: 13537-000
www.scodaeronautica.com.br

SB_SPLS_015
Revision 01

Page 4 de 5

Released Date: **June 23rd, 2020**
Effective Date: **July 09th, 2020**

1.12. Disclaimer

This Service Bulletin has been generated with utmost care. Nevertheless, errors and misunderstandings can never be fully excluded. In case of any doubts, the applicant is requested to contact Scoda Aeronáutica Ltda immediately to clarify the issue.

2. Resources

2.1. Parts

Engine Oil Decal (Qty. 1)

2.2. Special Tools

N/A

2.3. Manpower

N/A

2.4. Cost

N/A

SERVICE BULLETIN



Scoda Aeronáutica Ltda
Estrada Municipal IPN 020 km 0,1
Ipeúna – SP, Brazil.
PHONE: (19) 3576-1292
ZIP CODE: 13537-000
www.scodaeronautica.com.br

SB_SPLS_015
Revision 01

Page 5 de 5

Released Date: **June 23rd, 2020**
Effective Date: **July 09th, 2020**

3. Instructions

1. Engine oil decal should be installed on the upper engine cowling (see picture below).

NOTE

Clean the surface of the engine cowling before installing the decal.

