



SERVICE LETTER

Scoda Aeronáutica Ltda
Estrada Municipal IPN 020 km 0,1
Ipeúna – SP, Brazil.
PHONE: (19) 3576-1292
ZIP CODE: 13537-000
www.scodaeronautica.com.br

SL_SPLS_002
Revision 00

Released Date: **September 22nd, 2021**
Effective Date: **September 22nd, 2021**

Page 1 de 3

SERVICE LETTER

SL_SPLS_002

INSPECTION FOR APPLICABILITY OF ROTAX SB-912-075UL_SB-914-057UL

Application of Notes, Cautions and Warnings

NOTES, CAUTIONS and **WARNINGS** are used in this document to emphasize instructions and information considered to be unusual or critical. A **NOTE, CAUTIONS** and **WARNINGS** may appear in the text either before or after the instruction(s) to which it applies, depending on the relative significance of the information. The conditions that warrant the use of **NOTES, CAUTIONS** and **WARNINGS** are defined below:

WARNING

IDENTIFIES AN INSTRUCTION, WHICH IF NOT FOLLOWED MAY CAUSE SERIOUS INJURY OR EVEN DEATH

CAUTION

Denotes an instruction which if not followed, may severely damage the aircraft or could lead to suspension of warranty

NOTE

Information useful for better handling



SERVICE LETTER

Scoda Aeronáutica Ltda
Estrada Municipal IPN 020 km 0,1
Ipeúna – SP, Brazil.
PHONE: (19) 3576-1292
ZIP CODE: 13537-000
www.scodaeronautica.com.br

SL_SPLS_002
Revision 00

Page 2 de 3

Released Date: **September 22nd, 2021**
Effective Date: **September 22nd, 2021**

1. Planning Information

NOTE

SCODA AERONAUTICA cannot accept any responsibility for the quality of work performed. Please refer to the last revision of the Advisory Circular 43.13 – 1B Acceptable Methods, Techniques, and Practices Aircraft Inspection and Repair.

1.1. Affected Aircraft

Type:	Super Petrel
Model:	LS
Serial Number:	All aircraft affected by the referred Rotax Service Bulletin
Applicable Countries:	All

1.2. Reason

Rotax has issued a **MANDATORY** SB-912-075UL / SB-914-057UL for Engine Type 912 and 914 (Series), which is applicable to individual Super Petrel LS aircraft as indicated by:

- Engine Serial Number
- Carburetors or
- Spare Parts

1.3. Subject

Exchange of support spring on ROTAX® Engine Type 912 and 914 (Series).

1.4. Personnel Qualifications

According to Rotax SB instructions

1.5. References

- SB-912-075 / SB-914-057, Initial Issue September 10th, 2021
- SB-912-075UL / SB-914-057UL, Initial Issue September 10th, 2021

SERVICE LETTER

Scoda Aeronáutica Ltda
Estrada Municipal IPN 020 km 0,1
Ipeúna – SP, Brazil.
PHONE: (19) 3576-1292
ZIP CODE: 13537-000
www.scodaeronautica.com.br

SL_SPLS_002
Revision 00

Released Date: **September 22nd, 2021**
Effective Date: **September 22nd, 2021**

Page 3 de 3

1.6. Superseded Documents

N/A

1.7. Contact Details

For further information on performing this SL, contact us to the following email address:

engineering@scodaero.com.br

1.8. Disclaimer

This Service Letter has been generated with utmost care. Nevertheless errors and misunderstandings can never be fully excluded. In case of any doubts, the applicant is requested to contact Scoda Aeronáutica Ltda immediately to clarify the issue.