



## SERVICE LETTER

**Scoda Aeronáutica Ltda**  
Estrada Municipal IPN 020 km 0,1  
Ipeúna – SP, Brazil.  
PHONE: (19) 3576-1292  
ZIP CODE: 13537-000  
[www.scodaeronautica.com.br](http://www.scodaeronautica.com.br)

**SL\_SPLS\_001**  
**Revision 00**

Released Date: **December 03<sup>rd</sup>, 2020**  
Effective Date: **December 03<sup>rd</sup>, 2020**

Page 1 de 3

# SERVICE LETTER

**SL\_SPLS\_001**

## INSPECTION FOR APPLICABILITY OF ROTAX SB-912-074UL\_SB-914-056UL

### Application of Notes, Cautions and Warnings

**NOTES, CAUTIONS** and **WARNINGS** are used in this document to emphasize instructions and information considered to be unusual or critical. A **NOTE, CAUTIONS** and **WARNINGS** may appear in the text either before or after the instruction(s) to which it applies, depending on the relative significance of the information. The conditions that warrant the use of **NOTES, CAUTIONS** and **WARNINGS** are defined below:

### **WARNING**

**IDENTIFIES AN INSTRUCTION, WHICH IF NOT FOLLOWED MAY CAUSE SERIOUS INJURY OR EVEN DEATH**

### **CAUTION**

**Denotes an instruction which if not followed, may severely damage the aircraft or could lead to suspension of warranty**

### **NOTE**

Information useful for better handling



## SERVICE LETTER

**Scoda Aeronáutica Ltda**  
Estrada Municipal IPN 020 km 0,1  
Ipeúna – SP, Brazil.  
PHONE: (19) 3576-1292  
ZIP CODE: 13537-000  
[www.scodaeronautica.com.br](http://www.scodaeronautica.com.br)

**SL\_SPLS\_001**  
**Revision 00**

Page 2 de 3

Released Date: **December 03<sup>rd</sup>, 2020**  
Effective Date: **December 03<sup>rd</sup>, 2020**

### 1. Planning Information

#### NOTE

SCODA AERONAUTICA cannot accept any responsibility for the quality of work performed. Please refer to the last revision of the Advisory Circular 43.13 – 1B Acceptable Methods, Techniques, and Practices Aircraft Inspection and Repair.

#### 1.1. Affected Aircraft

Type:	Super Petrel
Model:	LS
Serial Number:	All aircraft affected by the referred Rotax Service Bulletin
Applicable Countries:	All

#### 1.2. Reason

Rotax has issued a **MANDATORY** SB-912-074UL / SB-914-056UL for Engine Type 912 and 914 (Series), which is applicable to individual Super Petrel LS aircraft as indicated by:

- Engine Serial Number
- Carburetors or
- Spare Parts

#### 1.3. Subject

Exchange of floats (pair) on ROTAX® Engine Type 912, 914 and 2-stroke (Series)

#### 1.4. Personnel Qualifications

According to Rotax SB instructions

#### 1.5. References

SB-912-074 / SB-914-055, Initial Issue December 03<sup>rd</sup>, 2020



## SERVICE LETTER

**Scoda Aeronáutica Ltda**  
Estrada Municipal IPN 020 km 0,1  
Ipeúna – SP, Brazil.  
PHONE: (19) 3576-1292  
ZIP CODE: 13537-000  
[www.scodaeronautica.com.br](http://www.scodaeronautica.com.br)

**SL\_SPLS\_001**  
**Revision 00**

Page 3 de 3

Released Date: **December 03<sup>rd</sup>, 2020**  
Effective Date: **December 03<sup>rd</sup>, 2020**

### 1.6. Superseded Documents

N/A

### 1.7. Contact Details

For further information on performing this SL, contact us to the following email address:

[engineering@scodaero.com.br](mailto:engineering@scodaero.com.br)

### 1.8. Disclaimer

This Service Letter has been generated with utmost care. Nevertheless errors and misunderstandings can never be fully excluded. In case of any doubts, the applicant is requested to contact Scoda Aeronáutica Ltda immediately to clarify the issue.