

LI_ENG_004	NOTICES OF CORRECTIVE ACTION INDEX PLEASE FIND LISTED BELOW ALL SAFETY ALERTS, SERVICE BULLETINS, SERVICE LETTERS AND NOTIFICATIONS RELEVANT FOR AIRCRAFT MODEL THE SUPER PETREL LS / SUPER PETREL XP								
Revision n°03									
Revision Date: February 05th, 2024									
Updated: August 05th, 2026									
Document Type	Document Code	Subject	Revision	Issue Date	Rev Date	Model	S/N of Affected Aircraft	Compliance	Status
1. SAFETY ALERTS	SA_SPLS_001	Inspection for Applicability of Rotax ASB-912i-011iSR1	2	11/29/2019	07/09/2020	Super Petrel LS	All aircraft equipped with the fuel pump assy. serial number affected by the referred Rotax Alert Service Bulletin	MANDATORY	RELEASED
	SA_SPLS_002	Rotax Fuel Pump Assy. Corrosion Inspection	0	06/08/2021	06/08/2021	Super Petrel LS	All aircraft equipped with Rotax 912 iS Sport Engine	MANDATORY	RELEASED
	SA_SPLS_003	Rotax Fine Fuel Filter Inspection	1	08/03/2022	07/25/2023	Super Petrel LS	All aircraft equipped with Rotax 912 iS Sport Engine	MANDATORY	RELEASED
	SA_SPLS_004	Wiring Harness Inspection	0	08/23/2023	08/23/2023	Super Petrel LS	All	MANDATORY	RELEASED
	SB_SPLS_001	RESERVED							
	SB_SPLS_002	RESERVED							
	SB_SPLS_003	RESERVED							
	SB_SPLS_004	Carburetor Heater Installation	1	02/22/2013	07/09/2020	Super Petrel LS	All	RECOMMENDED	RELEASED
	SB_SPLS_005	Rubber Foam Strip Installation	1	03/11/2013	07/09/2020	Super Petrel LS	All	RECOMMENDED	RELEASED
	SB_SPLS_006	BRS Parachute Rocket Release Hole	1	05/18/2015	07/09/2020	Super Petrel LS	S0208, S0209, S0210, S0211, S0215, S0218, S0221, S0222, S0237, S0239, S0250, S0262, S0266, S0276, S0288, S0297, S0302, S0309, S0310, S0317, S0320, S0324, S0327	MANDATORY	RELEASED
	SB_SPLS_007	RESERVED							
	SB_SPLS_008	Nose Gear Rubber Stop Replacement	1	10/09/2015	07/09/2020	Super Petrel LS	S0338, S0339, S0340, S0343, S0344	MANDATORY	RELEASED
	SB_SPLS_009	CHT Gauge Alteration	1	11/05/2015	07/09/2020	Super Petrel LS	S0299, S0306, S0307, S0308, S0309, S0310, S0311, S0312, S0313, S0314, S0315, S0316, S0317, S0318, S0319, S0320, S0321, S0322, S0323, S0324, S0325, S0326, S0327, S0328, S0329, S0330	MANDATORY	RELEASED
	SB_SPLS_010	Fuel Pumps and TCU Switches Replacement	2	30/01/2017	07/09/2020	Super Petrel LS	S0281, S0287, S0297, S0298, S0299, S0313, S0314, S0315, S0316, S0317, S0318, S0319, S0320, S0321, S0323, S0325, S0327, S0328, S0330, S0333, S0334, S0336, S0338	MANDATORY	RELEASED
	SB_SPLS_012	Fuel Filter Exchange	1	07/03/2017	07/09/2020	Super Petrel LS	All	MANDATORY	RELEASED

LI_ENG_004	NOTICES OF CORRECTIVE ACTION INDEX PLEASE FIND LISTED BELOW ALL SAFETY ALERTS, SERVICE BULLETINS, SERVICE LETTERS AND NOTIFICATIONS RELEVANT FOR AIRCRAFT MODEL THE SUPER PETREL LS / SUPER PETREL XP								
Revision n°03									
Revision Date: February 05th, 2024									
Updated: August 05th, 2026									
Document Type	Document Code	Subject	Revision	Issue Date	Rev Date	Model	S/N of Affected Aircraft	Compliance	Status
2. SERVICE BULLETINS	SB_SPLS_013	RESERVED							
	SB_SPLS_014	UMA Fuel Pressure Sensor Installation	1	02/12/2020	07/09/2020	Super Petrel LS	All aircraft serial number up to S0366 inclusive, equipped with <u>Rotax 912iS Sport Engine and Garmin G3X System.</u>	RECOMMENDED	RELEASED
	SB_SPLS_015	Engine Oil Decal	0	06/24/2020	07/09/2020	Super Petrel LS	All	RECOMMENDED	RELEASED
	SB_SPLS_016	Fuel Venting System	0	04/15/2021	04/15/2021	Super Petrel LS	From S0208 up to S0377 inclusive	RECOMMENDED	RELEASED
	SB_SPLS_017	Air Filter 912iS-914UL	0	05/12/2022	05/12/2022	Super Petrel LS	All aircraft equipped with Rotax 914 UL and 912 iS Sport	MANDATORY	RELEASED
	SB_SPLS_018	Airbox Inspection 914 UL	1	05/23/2023	06/01/2023	Super Petrel LS	All aircraft equipped with Rotax 914 UL	MANDATORY	RELEASED
	SB_SPLS_019	DUC Propeller Inspection	0	12/04/2024	12/04/2024	Super Petrel LS	All aircraft equipped with DUC Propeller FLASH-2	RECOMMENDED	RELEASED
	SB_SPLS_020	Wing Sponsor Mirror	0	03/07/2025	03/07/2025	Super Petrel LS	All	OPTIONAL	RELEASED
	SB_SPLS_021	ELT Antenna Replacement	0	08/14/2025	08/14/2025	Super Petrel XP	All aircraft equipped with Emergency Locator Transmitter (ELT)	OPTIONAL	RELEASED
	SB_SPXP_001	Nose Air Vent System Upgrade	1	09/30/2024	03/07/2025	Super Petrel XP	From S/N S0405 up to S0414 inclusive	MANDATORY	RELEASED
	SB_SPXP_002	FAA Weight Exemption-POH Update	0	11/21/2024	11/21/2024	Super Petrel XP	From S/N S0405 up to S0412 inclusive	OPTIONAL	RELEASED
	SB_SPXP_003	Led Cockpit Light	0	12/10/2024	12/10/2024	Super Petrel XP	From S/N S0405 up to S0410 inclusive	OPTIONAL	RELEASED
	SB_SPXP_004	Firewall Retrofit and Standardization	0	04/03/2025	04/03/2025	Super Petrel XP	From S/N S0405 up to S0414 inclusive	MANDATORY	RELEASED
	SB_SPXP_005	Cabin Heater Hose Clearance – Engine Cowling	0	04/07/2025	04/07/2025	Super Petrel XP	From S/N S0405 up to S0414 inclusive	MANDATORY	RELEASED
	SB_SPXP_006	Landing Gear Actuators Replacement	1	02/17/2026	08/14/2025	Super Petrel XP	From S/N S0405 up to S0416 inclusive	RECOMMENDED	RELEASED
	SB_SPXP_007	ELT Antenna Replacement	0	08/14/2025	08/14/2025	Super Petrel XP	From S/N S0405 up to S0418 inclusive	OPTIONAL	RELEASED
	SB_SPXP_008	New Torque Setting - Propeller Inner Bolts	1	10/14/2025	10/16/2025	Super Petrel XP	All	MANDATORY	RELEASED
	SB_SPXP_009	Canopy Rail Retrofit	0	11/03/2025	11/03/2025	Super Petrel XP	From S/N S0405 up to S0412 inclusive	MANDATORY	RELEASED
	SB_SPXP_010	Engine Cooling Baffle	0	08/05/2026	08/05/2026	Super Petrel XP	From S/N 404 up to S0428	OPTIONAL	RELEASED
	SL_SPLS_001	Inspection for Applicability of Rotax SB-912-074UL_SB-914-056UL	0	12/03/2020	12/03/2020	Super Petrel LS	All aircraft affected by the referred Rotax Service Bulletin	INFORMATION	RELEASED
	SL_SPLS_002	Inspection for Applicability of Rotax SB-912-075UL_SB-914-057UL	0	09/22/2021	09/22/2021	Super Petrel LS	All aircraft affected by the referred Rotax Service Bulletin	INFORMATION	RELEASED
	SL_SPLS_003	Maintenance Manual New Revision	0	03/16/2022	03/16/2022	Super Petrel LS	All	INFORMATION	RELEASED

LI_ENG_004	NOTICES OF CORRECTIVE ACTION INDEX PLEASE FIND LISTED BELOW ALL SAFETY ALERTS, SERVICE BULLETINS, SERVICE LETTERS AND NOTIFICATIONS RELEVANT FOR AIRCRAFT MODEL THE SUPER PETREL LS / SUPER PETREL XP								
Revision n°03									
Revision Date: February 05th, 2024									
Updated: August 05th, 2026									
Document Type	Document Code	Subject	Revision	Issue Date	Rev Date	Model	S/N of Affected Aircraft	Compliance	Status
3. SERVICE LETTERS	SL_SPLS_004	Inspection for Applicability of Rotax SB-912i-013	0	04/18/2022	04/18/2022	Super Petrel LS	All aircraft affected by the referred Rotax Service Bulletin	INFORMATION	RELEASED
	SL_SPLS_005	Maintenance Manual New Revision (Rev08)	0	11/04/2022	11/04/2022	Super Petrel LS	All	INFORMATION	RELEASED
	SL_SPLS_006	Inspection for Applicability of Garmin SB 22112 RevA	0	12/01/2022	12/01/2022	Super Petrel LS	All aircraft affected by the referred Garmin Service Bulletin	INFORMATION	RELEASED
	SL_SPLS_007	Mandatory Garmin Service Bulletin 22016-Autopilot Servo	0	05/09/2023	05/09/2023	Super Petrel LS	All Super Petrel LS equipped with Garmin G3X System	INFORMATION	RELEASED
	SL_SPLS_008	Inspection for Applicability of Rotax SB-912i-016 915i-016 916i-006	0	12/17/2024	12/17/2024	Super Petrel LS	All aircraft affected by the referred Rotax Service Bulletin	INFORMATION	RELEASED
	SL_SPXP_001	Garmin Service Alert 24070 Rev A-GHA15	0	12/03/2024	12/03/2024	Super Petrel XP	All Super Petrel XP equipped with GHA15	INFORMATION	RELEASED
	SL_SPXP_002	Inspection for Applicability of Rotax SB-912i-016 915i-016 916i-006	0	12/17/2024	12/17/2024	Super Petrel XP	All aircraft affected by the referred Rotax Service Bulletin	INFORMATION	RELEASED
	SL_SPXP_003	Inspection for Applicability of Rotax SB-912i-017 915i-017 916i-007	0	02/03/2024	02/03/2024	Super Petrel XP	All aircraft affected by the referred Rotax Service Bulletin	INFORMATION	RELEASED
	SL_SPXP_004	Aircraft Battery Discharge	0	05/02/2025	05/02/2025	Super Petrel XP	From S/N S0405 up to S0414 inclusive	INFORMATION	RELEASED
	SL_SPXP_005	Canopy Burning Glass Effect	0	05/02/2025	05/02/2025	Super Petrel XP	All	INFORMATION	RELEASED
	SL_SPXP_006	Maintenance Manual New Revision (Rev03)	0	05/09/2025	05/09/2025	Super Petrel XP	All	INFORMATION	RELEASED
	SL_SPXP_007	Maintenance Manual New Revision (Rev05)	0	01/29/2026	01/29/2026	Super Petrel XP	All	INFORMATION	RELEASED
4. NOTIFICATIONS	NT_SPLS_001	Technical Publications	1	10/06/2016	07/09/2020	Super Petrel LS	All	INFORMATION	RELEASED
	NT_SPLS_002	914 Engine Operation	1	12/16/2016	07/09/2020	Super Petrel LS	S0281, S0287, S0297, S0298, S0299, S0313, S0314, S0315, S0316, S0317, S0318, S0319, S0320, S0321, S0323, S0325, S0327, S0328, S0330, S0333, S0334, S0336, S0338	INFORMATION	RELEASED
	NT_SPLS_003	New Tire Pressures	1	06/07/2017	07/09/2020	Super Petrel LS	All	INFORMATION	RELEASED
	NT_SPLS_004	Inspection for Applicability of Rotax ASB-912i-007iS	1	06/09/2017	07/09/2020	Super Petrel LS	S0342, S0349, S0350	INFORMATION	RELEASED
	NT_SPLS_005	Inspection for Applicability of Rotax SB-912i-008iS_SB-912-070_SB-914-052UL	1	10/23/2017	07/09/2020	Super Petrel LS	All aircraft equipped with the engine serial number affected by the referred Rotax Service Bulletin	INFORMATION	RELEASED
	NT_SPLS_006	Brake Caliper Screws	1	07/30/2017	07/09/2020	Super Petrel LS	All	INFORMATION	RELEASED
	NT_SPLS_007	Maintenance Manual New Version	1	11/07/2018	07/09/2020	Super Petrel LS	All	INFORMATION	RELEASED

LI_ENG_004	NOTICES OF CORRECTIVE ACTION INDEX PLEASE FIND LISTED BELOW ALL SAFETY ALERTS, SERVICE BULLETINS, SERVICE LETTERS AND NOTIFICATIONS RELEVANT FOR AIRCRAFT MODEL THE SUPER PETREL LS / SUPER PETREL XP								
Revision n°03									
Revision Date: February 05th, 2024									
Updated: August 05th, 2026									
Document Type	Document Code	Subject	Revision	Issue Date	Rev Date	Model	S/N of Affected Aircraft	Compliance	Status
	NT_SPLS_008	Fuel Indication	1	02/28/2019	07/09/2020	Super Petrel LS	From S0295 inclusive	INFORMATION	RELEASED
	NT_SPLS_009	Inspection for Applicability of Rotax ASB-912i-010iS	1	03/14/2019	07/09/2020	Super Petrel LS	All aircraft equipped with the fuel pump assy. serial number affected by the referred Rotax Alert Service Bulletin	INFORMATION	RELEASED
	NT_SPLS_010	Inspection for Applicability of Rotax SB-912-073UL_SB-914-055UL	1	07/29/2019	07/09/2020	Super Petrel LS	All aircraft equipped with the fuel pump assy. serial number affected by the referred Rotax Service Bulletin	INFORMATION	RELEASED
	NT_SPLS_011	Maintenance Manual New Revision (Rev 01)	1	08/13/2019	07/09/2020	Super Petrel LS	All	INFORMATION	RELEASED
5. SERVICE INSTRUCTIONS	SI_SPLS_001	Hot Kit Installation Procedure	1	03/26/2019	07/09/2020	Super Petrel LS	All serial number equipped with Rotax 912 iS Sport Engine	RECOMMENDED	RELEASED
	SI_SPLS_002	Fuel Sensor Unit Replacement	2	09/17/2019	25/11/2021	Super Petrel LS	All	RECOMMENDED	RELEASED
	SI_SPLS_003	RESERVED							
	SI_SPLS_004	RESERVED							
	SI_SPLS_005	Landing Gear Position Alert - G3X System	0	01/25/2023	01/25/2023	Super Petrel LS	All aircraft equipped with <u>Garmin G3X System</u> .	RECOMMENDED	RELEASED
	SI_SPLS_006	Leakage Repair - Wing Fuel Tank	1	04/03/2025	04/11/2025	Super Petrel LS	All	INFORMATION	RELEASED
	SI_SPXP_001	Systems Upgrade & Release of the POH Revision_01	0	08/23/2024	08/23/2024	Super Petrel XP	S0405, S0406, S0407 and S0408	MANDATORY	RELEASED