



LI_ENG_004	NOTICES OF CORRECTIVE ACTION INDEX							
Revision n°00								
Initial Issue Date: Feb 19th, 2013								
Updated: October 17th, 2017								
PLEASE FIND LISTED BELOW ALL NOTIFICATIONS, SAFETY ALERTS AND SERVICE BULLETINS RELEVANT FOR THE SUPER PETREL LS QUALIFIED TO THE LSA REQUIREMENTS								
Document Type	Document Code	Subject	Revision	Issue Date	Model	S/N of Affected Aircraft	Compliance	Status
1. SAFETY ALERTS								
2. SERVICE BULLETINS	SB_SPLS_001	RESERVED						
	SB_SPLS_002	RESERVED						
	SB_SPLS_003	RESERVED						
	SB_SPLS_004	Carburetor Heater Installation	0	02/22/2013	Super Petrel LS	All	RECOMMENDED	RELEASED
	SB_SPLS_005	Rubber Foam Strip Installation	0	03/11/2013	Super Petrel LS	All	RECOMMENDED	RELEASED
	SB_SPLS_006	BRS Parachute Rocket Release Hole	0	05/18/2015	Super Petrel LS	S0208, S0209, S0210, S0211, S0215, S0218, S0221, S0222, S0237, S0239, S0250, S0262, S0266, S0276, S0288, S0297, S0302, S0309, S0310, S0317, S0320, S0324, S0327	MANDATORY	RELEASED
	SB_SPLS_007	RESERVED						
	SB_SPLS_008	Nose Gear Rubber Stop Replacement	0	10/09/2015	Super Petrel LS	S0338, S0339, S0340, S0343, S0344	MANDATORY	RELEASED
	SB_SPLS_009	CHT Gauge Alteration	0	11/05/2015	Super Petrel LS	S0299, S0306, S0307, S0308, S0309, S0310, S0311, S0312, S0313, S0314, S0315, S0316, S0317, S0318, S0319, S0320, S0321, S0322, S0323, S0324, S0325, S0326, S0327, S0328, S0329, S0330	MANDATORY	RELEASED
	SB_SPLS_010	Fuel Pumps and TCU Switches Replacement	1	30/01/2017	Super Petrel LS	S0281, S0287, S0297, S0298, S0299, S0313, S0314, S0315, S0316, S0317, S0318, S0319, S0320, S0321, S0323, S0325, S0327, S0328, S0330, S0333, S0334, S0336, S0338	MANDATORY	RELEASED
	SB_SPLS_011	RESERVED						
	SB_SPLS_012	Fuel Filter Exchange	0	07/03/2017	Super Petrel LS	All	MANDATORY	RELEASED
	SB_SPLS_013	RESERVED						

LI_ENG_004	NOTICES OF CORRECTIVE ACTION INDEX								
Revision n°00									
Initial Issue Date: Feb 19th, 2013 Updated: October 17th, 2017									
		PLEASE FIND LISTED BELOW ALL NOTIFICATIONS, SAFETY ALERTS AND SERVICE BULLETINS RELEVANT FOR THE SUPER PETREL LS QUALIFIED TO THE LSA REQUIREMENTS							
Document Type	Document Code	Subject	Revision	Issue Date	Model	S/N of Affected Aircraft	Compliance	Status	
3. NOTIFICATIONS	NT_SPLS_001	Technical Publications	0	10/06/2016	Super Petrel LS	All	INFORMATION	RELEASED	
	NT_SPLS_002	914 Engine Operation	0	12/16/2016	Super Petrel LS	S0281, S0287, S0297, S0298, S0299, S0313, S0314, S0315, S0316, S0317, S0318, S0319, S0320, S0321, S0323, S0325, S0327, S0328, S0330, S0333, S0334, S0336, S0338	INFORMATION	RELEASED	
	NT_SPLS_003	New Tire Pressures	0	06/07/2017	Super Petrel LS	All	INFORMATION	RELEASED	
	NT_SPLS_004	Inspection for Applicability of Rotax ASB-912i-007iS	0	06/09/2017	Super Petrel LS	S0342, S0349, S0350	INFORMATION	RELEASED	
	NT_SPLS_005	Inspection for Applicability of Rotax SB-912i-008iS_SB-912-070_SB-914-052UL	0	10/23/2017	Super Petrel LS	All aircraft equipped with the engine serial number affected by the referred Rotax Service Bulletin	INFORMATION	RELEASED	